

FLOW METER
AND
CALIBRATION POINT

HIGH PRESSURE
GAUGE
CALIBRATION
POINT


HIGH
PRESSURE
GAUGE
0-8000 PSI

CHAMBER
GAUGE
CALIBRATION
POINT

CHAMBER
GAUGE
0-50 PSI

LOW
PRESSURE
GAUGE
0-150 PSI

LOW PRESSURE
GAUGE
CALIBRATION
POINT



NEOMETRIX
www.neometrix.in

REPAIR OF KU-7 LEAK TESTER - BIDAR

NEOMETRIX ENGINEERING PVT. LTD.
E-148, Sector-63, Noida, UP-201301
Tel. No. : 0120-4500900
Fax No. : 0120-4500988
E-Mail: contact@neometrixindia.com

MAIN TITLE

Q.A. No.

SUB-TITLE

CONSISTENT DOC.

CODE

CUSTOMER

END-USER

NOTES

APPLICATION

PROTECTION

ISSUED BY

NO. OF

APPROVED BY

NEO DWG. NO.

DATE

Rev

SIZE

00